Applies to	:	Tubes SRO 09/50 and SRO 09/51 with Optimus generators
Short Description	:	SRO 09/50 tubes **must not** be used for Optimus RAD+/RF+C generators.
Symptom	:	The **SRO 09/50 tube (9874 007 01122)** has a resistor in line with the small focus. Optimus generators set a standby filament current which is much higher compared to predecessor generators. This leads to overheating of the oil and the tube housing.
Solution	:	The resistor in line with the small focus is not required in combination with an Optimus generator, therefore the tube type **SRO 09/51 (9890 00 63181)** is available which does not have this resistor. **Only this tube type must be used in combination with an Optimus.** SRO 09/50 does not exist in the compatibility list of Optimus generators since 1997.